

## State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

## Inspection Report Minerals Regulatory Program June 7, 2010

Reviewed:

Mine Name: West Side Mine

Operator Name: DJN Rockwalls

Inspection Date: 04/22/2010

Inspector(s): Leslie Heppler

Time: 9:00 am

Other Participants: None Mine Status: Active

|   |           | Time Status Tietre |            |  |
|---|-----------|--------------------|------------|--|
| Elements of Inspection  | Evaluated | Comment            | Enforcemen |  |
| <ol> <li>Permits, Revisions, Transfer, Bonds</li> <li>Public Safety (shafts, adits, trash, signs, highwalls)</li> <li>Protection of Drainages / Erosion Control</li> <li>Deleterious Material</li> <li>Roads (maintenance, surfacing, dust control, safety)</li> <li>Reclamation</li> <li>Backfilling/Grading (trenches, pits, roads, highwalls, solls</li> <li>Revegetation</li> </ol> | shafts)   |                    |            |  |

**Bond Renewal Date:** 04-06-2006 **Bond Amount:** \$8,000 **Permit fee** is delinquent from 2008 to 2009, the total due is \$300

**Purpose of Inspection:** Routine annual Inspection. This site was inspected as a small mine site on 10/27/2009

**Inspection Summary:** Another Operator has regraded this area. See photographs of the site. This site has yet to be reseeded. Scrub Oak slash can be added to the regraded area for additional growth.

Conclusions and Recommendations Operator needs to pay annual fees. Operator needs to reseed the site. Delinquent fees need to be paid. DOGM will continue to monitor this site until these issues are resolved. Operator has 30 days to comply with all local, state and federal rules.

**Inspector's Signature** 

LAH:vs

cc: Shane Nay

O:\M035-SaltLake\S350032-DJN\inspections\Insp-04222010.doc



